

Corrosion Report



Equipment Location ID 0955-014-002
 Equip. Location Descrip. C-1160 OUTLET TO C-1100

Remaining Life (Years) 19.52
 Retirement Date 11/10/2029
 Last Inspection Date 05/05/2010
 Next Inspection Date 02/06/2020
 Current Corrosion Rate 7.17

DP ID	MEAS METH	DP STAT	DP SZ	DT TYPE	BASE	MEAS 5	MEAS 4	MEAS 3	NEAR	LAST	MIN VALUE	CCR	REM LIFE
011.R	RT	A	4.00	ELL	0.250 11/03					0.250 03/10	0.100	0.00	∞
012.R	RT	A	4.00	ELL	0.280 10/04					0.240 05/10	0.100	7.17	19.52
013.R	RT	A	4.00	ELL	0.220 03/88				0.250 05/01	0.250 05/10	0.100	0.00	∞





History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	4/7/2008	Date Available:	04/07/2008
History Brief Date:	04/07/2008	History Brief ID:	VI-0804196915
Event Type:	Inspection	In- Service Date:	04/07/2008
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	09/11/2006
Asset Type:	221	Inspection Type:	EVI
Cost Center:	K.DCRRI00281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	RFMS CUI Project Inspection Results		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	PTS
Cause Category:	Information	Program Status:	
Effect Category:	Corrosion	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	CSAA
Save:		Inspected By:	CSAA

Findings:

PCA ID:

Inspectable:

Sub Item:

Part:

Discussion:

Condition:

Action:

Location:

Damage Mechanism:

PCA Work Order No :

Reliability Comments:

Insulation was removed from the TEE below TML 4 all the way to C-1100. Superficial CUI was noted on all exposed piping. The line was reinsulated from the TEE over to the vicinity of LV-072 for personnel protection. The remainder from LV-072 to C-1100 was left off permanently as per SME decision because this section of the circuit was out of service and blinded. No further action taken. UPDATE 04-07-08: this line was repaired during the last SD and put back into service. It was requested to reinsulate the entire line now that it is in service on 4-07-08.



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	3/6/2007	Date Available:	03/06/2007
History Brief Date:	03/06/2007	History Brief ID:	VI-0703170256
Event Type:	Information	In- Service Date:	03/06/2007
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	03/06/2007
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	Replaced leak clamped pipe per (HB-0010048125) 07 S/D.		

Reliability Analysis:

Event Type:	Information	Worked Performed By:	P2S
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Pipe Wall
Repair Location:	Field	Permanent Repair WO:	26206207
Temporary Repair:	No	Name:	STYR
Save:		Inspected By:	STYR

Findings:

PCA ID:
Inspectable:
Sub Item:
Part:
Discussion:

Condition:
Action:
Location:
Damage Mechanism:
PCA Work Order No :

Reliability Comments:

Per S/D EWO # BE 139-E1 the leak clamped elbow (See HB-0010048125 12/15/00) was replaced 2007 S/D.



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	1/6/2005	Date Available:	
History Brief Date:	01/11/2005	History Brief ID:	EI-0501118215
Event Type:	Inspection	In- Service Date:	
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	01/06/2005
Asset Type:	221	Inspection Type:	EVI
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	5 Year VT/CUI Insp		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron - General
Cause Category:	Compliance, Inspection, PM	Program Status:	
Effect Category:	No Effect	Maintainable Item:	General
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	JMJG
Save:		Inspected By:	

Reliability Comments:

Most of line is out of service; 525 deg F noted at only I/S portion (P-1178 and A discharges to E-1178 feed line). Blinded at LCV- 042.
For CUI insp: RT TML's 7, 8, 11, dead-leg support below TML 10 (no drain hole seen), and dead leg portion of line past E-1178 feed line branch connection.



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	7/17/2001	Date Available:	
History Brief Date:	07/17/2001	History Brief ID:	HB-0107056108
Event Type:	Inspection	In- Service Date:	
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR00281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	P-1178 improper materials.		

Reliability Analysis:

Event Type:	Inspection	Worked Performed By:	Chevron Operations
Cause Category:	Design	Program Status:	
Effect Category:	Information	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	GAKL
Save:		Inspected By:	

Findings:

PCA ID:
Inspectable:
Sub Item:
Part:
Discussion:

Condition:
Action:
Location:
Damage Mechanism:
PCA Work Order No :

Reliability Comments:

7/17/01 1:03:32 PM

The inspection department has found an improper line that has been installed from the pump outlet to a sample station and back to the pump inlet. This piping consists of threaded carbon steel pipe and fittings, all disallowed by the pipe class. a recommendation to remove or replace with proper materials has been written and issued.

This line is tied into the two 3/4" valves, one on the inlet and one on the outlet and also feeds the sample station. The 3/4" valve on the outlet side was PMI inspected back in 97'. It was found to be Carbon steel and was replaced during the 1-98' S/D. However the inlet side was either missed or as I believe didn't exist prior to the 98' S/D but rather was installed at that time. I base this on the fact that other items shown and not shown on the existing isometric were found to be improper and were replaced during the S/D. Unfortunately I can't find any evidence in the 98' S/D records of this valve and with the rest of this line being threaded
(disallowed per the pipe class) I have no idea how long it has been in service.

History Brief

For Location ID: 0955-014-002 in Unit: 0955



Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	10/18/2000	Date Available:	
History Brief Date:	10/21/2000	History Brief ID:	HB-0010048125
Event Type:	Failure	In- Service Date:	
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	Leak in overflash line to C-1100		

Reliability Analysis:

Event Type:	Failure	Worked Performed By:	Chevron Maintenance
Cause Category:	Information	Program Status:	
Effect Category:	Leak	Maintainable Item:	Pipe Wall
Repair Location:	Field	Permanent Repair WO:	
Temporary Repair:	Yes	Name:	JASA
Save:	No	Inspected By:	

Findings:

<u>PCA ID:</u>	<u>Condition:</u>
<u>Inspectable:</u>	<u>Action:</u>
<u>Sub Item:</u>	<u>Location:</u>
<u>Part:</u>	<u>Damage Mechanism:</u>
<u>Discussion:</u>	<u>PCA Work Order No :</u>

Reliability Comments:

10/18/2000 10:32:44 AM- A pinhole leak in the 4" overflash line to C-1100 developed in a weld of the pipe to elbow located in the overhead pipeway. This line is the P-1178 discharge through LV-1172 control manifold, (0955-014-002). The line was depressured by rerouting the overflash back to C-1160 (through E-1178). The isolation block valve at C-1100 didn't hold so C-1100 stock returned into the pipe. This lighter material leaked out of the hole rapidly and created a vapor cloud. Nitrogen was introduced to the line to push the C-1100 oil back into the column while the block valve at C-1100 was Kopple sealed tight. With the valve sealed, we still will leave N2 on the 4" line and clamp the leak.

The leaking weld and three other welds in the area were radiographed. The leaking weld was severely internally corroded but the other three welds showed no corrosion. It's thought that the failed weld is not 5Cr, however, records show that it was PMI inspected and it is 5Cr material. Along with leaving the line out of service and leaving a N2 purge on the line, we decided to install a clamp to keep the line together at the weld. We to PMI'd the weld prior to putting the clamp on it. The cover pass is 5Cr, somewhat diluted with the, what is believed to be, carbon steel inner passes. This failure needs to be removed on the shutdown and sent to the Materials Lab for failure analysis.

Naturally the results of the lab analysis will help develop a better inspection program, but we need to identify other corroded welds in this system now. We plan to start to look at some of the welds in this 5Cr system and start to develop what we need to bring this problem to closure.

12/15/00 10:23:20 AM

It was decided during the shutdown to leave the clamped failed elbow in place and not use the overflash line to the



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

atmospheric column. No inspection has been done on this line other than what was done mentioned above. We don't know if there is any more thin welds on this portion or the line. As for the rest of the overflash system, we RT'd what was available on the ground and found nothing. We probably covered 20% of the entire system.

Classification:

Method of Detection: Observation

What Happened when it Failed?

Equipment Unavailable: Yes - Line taken out of service

Unit Shutdown: No -

Process Disruption: No -

Safety Compromised: No -

Environmental Impact: No -

Impact Assoc. Processes: No -

What was the direct cause? High Temp H2S Corrosion

How did it fail? Leak

Why did it fail? Fabrication Error

Why did it fail description: we THINK the weld is not 5Cr

What is the failure type? Equipment

What was done to the asset? Removed From Service

Failure analysis date: 10/21/2000 12:00:00AM

failure Cost (\$):

History Brief Date: 12/15/2000

History Brief ID: HB-0012049547

Event Type: Failure

In- Service Date:

Equipment ID: 0955-014-002

Critical: L

Asset ID: 0000111052

Reference Material:

Work Order Nbr:

Incident Event ID:

History Type: FXD

Inspection Date:

Asset Type: 221

Inspection Type:

Cost Center: K.DCRR100281

Unit: 0955 - 4 CRUDE UNIT PLT 11

Headline: 0955-014-002 Check valve failed at column.

Reliability Analysis:

Event Type: Failure

Worked Performed By: Chevron Maintenance

Cause Category: Information

Program Status:

Effect Category: Information

Maintainable Item: Valves

Repair Location: Field

Permanent Repair WO:

Temporary Repair: No

Name: JASA

Save:

Inspected By:

Findings:



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

PCA ID:
Inspectable:
Sub Item:
Part:
Discussion:

Condition:
Action:
Location:
Damage Mechanism:
PCA Work Order No :

Reliability Comments:

The check valve flapper on the FV-1189 control valve manifold failed and the flapper has lodged up in the valve body. The valve was replaced on the Nov. 2000 shutdown and unfortunately the internals were missing when inspection found the valve body. A new 5Cr valve was installed.

Inspection should internally inspect these valves at the next shutdown to see if the pin and/or flapper are ok. This is one of two 5Cr valves that failed on the run and it's suspicious that both flappers failed. We wonder if the 5Cr valves we're getting in the refinery have the right metallurgy internally.

The other valve is on the overflash piping at the atmospheric column next to the block valve. 0955-014-002

Classification:

Method of Detection: Observation

What Happened when it Failed?

Equipment Unavailable:	Yes - the valve failed, it lost it's flapper
Unit Shutdown:	No -
Process Disruption:	Yes - could not send overflash back to the atmospheric column
Safety Compromised:	Yes - when the line was isolated the check valve allowed atmospheric stock to re-enter the line and leak out of the downstream failed weld
Environmental Impact:	Yes - hot gasses escaped the leak and nearly ignited
Impact Assoc. Processes:	No -
What was the direct cause?	High Temp H ₂ -H ₂ S Corrosion
How did it fail?	Mechanical Damage
Why did it fail?	Improper Material
Why did it fail description:	I'm guessing that the internals material isn't adequate for this service.
What is the failure type?	Equipment
What was done to the asset?	Replace
Failure analysis date:	12/15/2000 12:00:00AM
failure Cost (\$):	



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	1/27/1998	Date Available:	
History Brief Date:	07/08/2002	History Brief ID:	HB-0207073785
Event Type:	Information	In- Service Date:	
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR00281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	PMI		

Reliability Analysis:

Event Type:	Information	Worked Performed By:	Chevron Maintenance
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Pipe Wall
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	UNK
Save:		Inspected By:	

Findings:

PCA ID:

Inspectable:

Sub Item:

Part:

Discussion:

Condition:

Action:

Location:

Damage Mechanism:

PCA Work Order No :

Reliability Comments:

MATERIAL ANALYSIS ON THE FIVE CHROME PIPING SYSTEM REVEALED C/S VALVES AND VALVE BONNETS AT LOCATIONS 4,42, 52, 219, 127C, 98A-98G, AND 100A-100G COULD NOT BE EXAMINED DUE TO OBSTRUCTIONS.



History Brief

For Location ID: 0955-014-002 in Unit: 0955

Report Date: August 15, 2012

Data Source: Meridium

Brief Data:

Date Not Available:	1/1/1998	Date Available:	
History Brief Date:	10/24/2002	History Brief ID:	HB-0210080786
Event Type:	Information	In- Service Date:	
Equipment ID:	0955-014-002	Critical:	L
Asset ID:	0000111052	Reference Material:	
Work Order Nbr:		Incident Event ID:	
History Type:	FXD	Inspection Date:	
Asset Type:	221	Inspection Type:	
Cost Center:	K.DCRR100281		
Unit:	0955 - 4 CRUDE UNIT PLT 11		
Headline:	1998 Shut Down New Valves		

Reliability Analysis:

Event Type:	Information	Worked Performed By:	Chevron Maintenance
Cause Category:	Information	Program Status:	
Effect Category:	Information	Maintainable Item:	Valves
Repair Location:		Permanent Repair WO:	
Temporary Repair:		Name:	UNK
Save:		Inspected By:	

Findings:

<u>PCA ID:</u>	<u>Condition:</u>
<u>Inspectable:</u>	<u>Action:</u>
<u>Sub Item:</u>	<u>Location:</u>
<u>Part:</u>	<u>Damage Mechanism:</u>
<u>Discussion:</u>	<u>PCA Work Order No :</u>

Reliability Comments: